

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
.18 x .35	3	12	0.25	0.1292	92	WR-111	650	0.06
.2 x .4	2	19	0.25	0.11316	78	FLX-74	Mark Andy	RECTANGLE
.2 x .75	3	12	0.125	0.125	168	FLX-25	650	0.0625
.20 x 3.5	2	2	0.25	0.125	116	6WR-186	650	0.03125
.302 x 1.25	2	7	0.125	0.25	168	FLX-46	650	0.0625
.365 x 1.615	2	6	0.125	0.135	168	FLX-18	650	0.0625
.375 x 1	2	7	0.125	0.125	126	6WR-211	650	0.03125
.375 x 1.5	2	4	0.125	0.125	52	MA-235	Mark Andy	RECTANGLE
.375 x 3	3	2	0.125	0.125	100	6WR-294	650	0.027
.375 x 3	3	2	0.125	0.125	50	MA-182	Mark Andy	RECTANGLE
.5 x .5	4	17	0.25	0.1176	84	FLX-58	Mark Andy	0.0156
.50 x 1.25	2	5	0.125	0.125	110	6WR-215	650	0.0625
.50 x 1.25	6	4	0.125	0.125	88	6WR-310	650	0.0625
.50 x 1.5	2	4	0.125	0.125	104	WR-32	650	0.0625
.50 x 1.75	4	5	0.125	0.125	75	PR-39	Propheteer	0.125
.5 x 1.75	4	5	0.125	0.125	75	MA-525	Mark Andy	0.125
.50 x 1.9375	4	3	0.125	0.1875	102	WR-1	650	0.0625
.50 x 2	2	3	0.125	0.125	102	WR-128	650	0.125
.50 x 2.5	1	3	0.125	0.125	126	WR-29	650	0.0625
.5 x 6.25	4	1	0.125	0.125	51	MA-538	Mark Andy	0.0625
.62 X .78	2	12	0.125	0.095	168	FLX-30	650	0.0625
.62 x 2.62	4	2	0.125	0.13	88	6WR-261	650	0.125
.625 x 1.125	3	5	0.125	0.125	50	MA-178	Mark Andy	RECTANGLE
.625 x 1.75	2	4	0.125	0.125	120	WR-34	650	0.0625
.625 x 2.5	3	2	0.125	0.125	42	MA-102	Mark Andy	RECTANGLE
.6406 x .6406	6	8	0.125	0.125	49	MA-358	Mark Andy	0.0625
.6875 x 4.25	2	2	0.125	0.125	70	MA-206	Mark Andy	RECTANGLE
.6875 x 6	2	1	0.125	0.125	49	MA-148	Mark Andy	RECTANGLE
.70 x 8.5	4	1	0.125	0.125	69	MA-589	Mark Andy	RECTANGLE
.75 x .375	1	12	0	0.125	96	WR-53	650	0.046875
.75 x .5	4	8	0.25	0.125	80	WR-59	650	0.125
.75 X .75	2	12	0.125	0.125	168	FLX-37	650	0.0625
.75 x .75	3	6	0.125	0.1875	45	MA-163	Mark Andy	RECTANGLE
.75 x 1.25	3	5	0.125	0.125	55	MA-232	Mark Andy	RECTANGLE
.75 x 1.5	3	4	0.125	0.125	104	6WR-194	650	0.125
.75 x 1.75	2	5	0.125	0.35	168	FLX-41	650	0.125
.75 x 2	6	3	0.125	0.125	51	MA-360	Mark Andy	0.125
.75 x 2.5	1	3	0	0.125	126	WR-33	650	0.0625
.75 x 2.5	1	3	0	0.125	126	WR-46	650	0.125
.75 x 3.75	1	2	0	0.125	124	WR-58	650	0.015625
.75 x 3.75	4	2	0.125	0.125	62	MA-584	Mark Andy	0.125
.75 x 6.5	2	1	0.125	0.125	53	MA-13	Mark Andy	RECTANGLE
.80 x 1.08	3	5	0.125	0.12	96	6WR-289	650	0.125
.8125 x 1	2	5	0.125	0.125	90	WR-76	650	0.125
.8125 x 1	2	5	0.25	0.125	90	WR-77	650	0.03125
.8125 x 1.375	3	4	0.125	125	48	MA-199	Mark Andy	RECTANGLE
.8125 x 1.8125	2	4	0.25	0.125	124	WR-78-1	650	0.03125
.8125 x 3.25	2	2	0.125	0.125	54	MA-220	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
.8125 x 6.5	2	1	0.125	0.125	53	MA-79	Mark Andy	RECTANGLE
.875 x 3	2	2	0.125	0.125	100	6WR-193	650	0.125
.875 x 3.25	2	2	0.125	0.125	54	MA-10	Mark Andy	RECTANGLE
.875 x 4.75	2	2	0.125	0.125	78	MA-99	Mark Andy	RECTANGLE
.875 x 5	1	2	0	0.125	164	6WR-206	650	0.125
.875 x 8.5	4	1	0.125	0.125	69	MA-396	Mark Andy	RECTANGLE
.875 x 11.75	4	1	0.125	0.125	95	MA-588	Mark Andy	0.125
.875 x 11.875	3	1	0.125	0.125	192	6WR-243	650	0.03125
.90 x 13.25	4	1	0.125	0.25	108	MA-592	Mark Andy	RECTANGLE
1 x .25	2	14	0.125	0.125	84	WR-83	650	0.09375
1 X .25	3	14	0.125	0.125	84	6WR-217	for 50lb linear	0.0312
1 x .375	2	21	0.125	0.125	168	FLX-35	650	0.0625
1 x .875	2	7	0.125	0.125	112	6WR-269	650	0.125
1 x .875	2	6	0.125	0.125	96	WR-71	650	0.0625
1 x 1	4	6	0.125	0.125	54	MA-350	Mark Andy	0.0625
1 x 1.5	3	4	0.125	0.125	52	MA-313	Mark Andy	0.1875
1 x 1.5	1	5	0	0.125	130	WR-49	650	0.062
1 x 1.75	3	4	0.125	0.125	120	6WR-275	650	0.125
1 x 2	2	3	0.125	0.125	102	6WR-230	650	0.125
1 x 2	3	3	0.125	0.125	102	6WR-247	650	0.125
1 x 2	1	3	0	0.125	102	WR-37	650	0.125
1 x 2.5	3	3	0.125	0.125	126	6WR-224	650	0.125
1 x 3	3	2	0.125	0.125	100	6WR-293	650	0.125
1 x 3	3	2	0.125	0.125	100	WR-3	650	squared
1 x 3.5	3	2	0.125	0.125	116	6WR-260	650	0.125
1 x 3.75	3	2	0.125	0.125	62	MA-225	Mark Andy	RECTANGLE
1 x 4	4	2	0.125	0.125	132	6WR-321	650	0.125
1 x 4.5	2	2	0.125	0.125	74	MA-204	Mark Andy	RECTANGLE
1 x 5	2	1	0.125	0.125	41	MA-128	Mark Andy	RECTANGLE
1 x 5.5	2	1	0.125	0.125	45	MA-63	Mark Andy	RECTANGLE
1 x 6	3	1	0.125	0.125	49	MA-426	Mark Andy	0.125
1 x 6.25	2	1	0.125	0.125	102	WR-4	650	squared
1 x 6.25	2	1	0.125	0.125	51	MA-135	Mark Andy	RECTANGLE
1 x 6.5	2	1	0.125	0.125	53	MA-81	Mark Andy	RECTANGLE
1 x 7	2	1	0.125	0.125	57	MA-117	Mark Andy	RECTANGLE
1 x 8	4	1	0.125	0.125	65	MA-391	Mark Andy	0.125
1 x 8	1	1	0	0.125	130	WR-62	650	squared
1.125 x .5	2	14	0.125	0.25	168	FLX-21	650	0.0625
1.125 x .625	3	7	0.125	0.125	42	MA-06	Mark Andy	RECTANGLE
1.125 x .6875	2	14	0.125	0.0625	168	FLX-20	650	0.03125
1.125 x 1.125	3	8	0.125	0.1875	168	FLX-28	650	0.09375
1.125 x 1.5	4	4	0.125	0.125	52	MA-71	Mark Andy	RECTANGLE
1.125 x 1.625	2	4	0.125	0.125	56	MA-51	Mark Andy	RECTANGLE
1.125 x 2	2	3	0.125	0.125	102	6WR-179	650	0.125
1.125 x 2.25	2	3	0.125	0.125	57	MA-228	Mark Andy	RECTANGLE
1.125 x 2.5	2	3	0.125	0.125	63	MA-42	Mark Andy	RECTANGLE
1.125 x 2.5	2	2	0.125	0.125	42	MA-112	Mark Andy	RECTANGLE
1.125 x 2.625	3	3	0.125	0.125	66	MA-509	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
1.125 x 3	2	2	0.125	0.125	50	MA-62	Mark Andy	RECTANGLE
1.125 x 3.375	2	2	0.125	0.125	56	MA-61	Mark Andy	RECTANGLE
1.125 x 4.25	2	2	0.125	0.125	70	MA-30	Mark Andy	RECTANGLE
1.125 x 4.25	2	2	0.125	0.125	70	MA-201	Mark Andy	RECTANGLE
1.125 x 4.75	4	2	0.125	0.125	78	MA-280	Mark Andy	RECTANGLE
1.125 x 4.875	2	2	0.125	0.125	80	MA-209	Mark Andy	RECTANGLE
1.125 x 6.25	2	1	0.125	0.125	102	WR-164	650	0.125
1.161 x .767	1	7	0	0.108	98	WR-60	650	0.125
1.1875 x 1.875	2	3	0.125	0.125	96	WR-6	650	0.1875
1.1875 x 6.5	2	1	0.125	0.125	53	MA-142	Mark Andy	RECTANGLE
1.20 x 1.12	2	5	0.125	0.13	100	6WR-288	650	0.125
1.25 x .25	1	14	0	0.125	84	6WR-272	650	0.03125
1.25 x .4375	2	10	0.125	0.125	90	6WR-219	650	0.0625
1.25 x .5625	2	10	0.125	0.125	110	6WR-212	650	0.125
1.25 x .75	2	12	0.125	0.125	168	FLX-23	650	0.125
1.25 x 1.25	2	7	0.125	0.25	168	FLX-36	650	0.125
1.25 x 2	2	3	0.125	0.125	51	MA-193	Mark Andy	RECTANGLE
1.25 x 2.25	2	3	0.125	0.125	114	6WR-240	650	0.125
1.25 x 2.375	2	3	0.125	0.125	60	MA-59	Mark Andy	RECTANGLE
1.25 x 2.5	2	3	0.125	0.125	63	MA-507	Mark Andy	0.03125
1.25 x 2.75	3	3	0.25	0.125	69	PR-40	Propheteer	0.0625
1.25 x 2.8125	2	2	0.125	0.125	94	6WR-241	650	0.125
1.25 x 3	2	3	0.125	0.125	150	6WR-264	650	0.125
1.25 x 3	2	2	0.125	0.125	50	MA-03	Mark Andy	RECTANGLE
1.25 x 3.25	2	2	0.125	0.125	54	MA-19	Mark Andy	RECTANGLE
1.25 x 4	2	2	0.125	0.125	132	6WR-188	650	0.125
1.25 x 4	2	2	0.125	0.125	132	WR-165	650	0.125
1.25 x 4.25	2	2	0.125	0.125	70	MA-160	Mark Andy	RECTANGLE
1.25 x 4.75	2	2	0.125	0.125	156	6WR-250	650	0.125
1.25 x 5	2	1	0.125	0.125	41	MA-157	Mark Andy	RECTANGLE
1.25 x 5	2	1	0	0.125	41	MA-171	Mark Andy	RECTANGLE
1.25 x 5.5	2	1	0.125	0.125	45	MA-12	Mark Andy	RECTANGLE
1.25 x 6	3	1	0.125	0.125	98	6WR-251	650	0.125
1.28 x 2.35	1	2	0	0.15	80	WR-36	650	squared
1.3125 x .25	2	28	0.125	0.125	168	FLX-22	650	0.0625
1.3125 x 1.9375	1	4	0	0.125	66	MA-122	Mark Andy	RECTANGLE
1.3125 x 2.25	2	3	0.125	0.125	57	MA-48	Mark Andy	RECTANGLE
1.3125 x 2.3125	2	3	0.125	0.1458	59	MA-40	Mark Andy	RECTANGLE
1.3125 x 3	2	2	0.125	0.125	50	MA-75	Mark Andy	RECTANGLE
1.3125 x 7.5	2	1	0.125	0.125	61	MA-229	Mark Andy	RECTANGLE
1.32 x 2	2	3	0.125	0.125	102	6WR-295	650	0.125
1.375 x .375	2	12	0.125	0.125	96	WR-153	650	0.062
1.375 x 1.8125	1	3	0	0.1458	94	WR-61	650	0.046875
1.375 x 3.25	2	2	0.125	0.125	54	MA-84	Mark Andy	RECTANGLE
1.375 x 3.2987	3	2	0.125	0.1388	55	MA-510	Mark Andy	RECTANGLE
1.375 x 3.375	2	2	0.125	0.125	112	WR-156	650	0.0312
1.375 x 3.875	1	2	0	0.125	128	WR-50	650	0.0625
1.375 x 4	1	2	0	0.125	132	WR-161	650	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
1.375 x 4	1	2	0	0.125	132	WR-26	650	0.1875
1.375 x 4	2	2	0.125	0.125	66	MA-80	Mark Andy	RECTANGLE
1.375 x 4.625	4	2	0.125	0.125	76	MA-427	Mark Andy	RECTANGLE
1.375 x 6.25	2	1	0.125	0.125	51	MA-119	Mark Andy	RECTANGLE
1.375 x 8.125	2	1	0.125	0.125	132	WR-5	650	0.125
1.375 x 8.625	2	1	0.125	0.125	70	MA-180	Mark Andy	RECTANGLE
1.375 x 10.875	1	1	0	0.125	176	6WR-271	650	0.03125
1.40 x 3.10	1	3	0	0.15	156	WR-30	650	0.09375
1.4375 x .4375	4	10	0.125	0.125	90	6WR-281	650	0.0625
1.4375 x 3.25	2	2	0.125	0.125	54	MA-143	Mark Andy	RECTANGLE
1.4375 x 3.625	2	2	0.125	0.125	60	MA-29	Mark Andy	RECTANGLE
1.4375 x 4.75	2	2	0.125	0.125	78	MA-89	Mark Andy	RECTANGLE
1.45 x 3.62	1	2	0	0.13	120	WR-147	650	0.125
1.49 X 1.93	3	5	0.125	0.17	168	FLX-13	650	0.125
1.5 x .4375	3	12	0.125	0.125	54	MA-494	Mark Andy	0.125
1.5 x .625	1	8	0	0.125	96	WR-44	650	0.125
1.5 x .625	3	9	0.125	0.125	54	MA-500	Mark Andy	0.125
1.5 x .75	3	8	0.125	0.125	56	MA-495	Mark Andy	0.125
1.5 x .75	1	8	0	0.125	112	WR-136	650	0.31
1.5 x 1	3	6	0.125	0.125	54	MA-404	Mark Andy	0.125
1.5 x 1	1	5	0	0.125	90	WR-73	650	0.03125
1.5 x 1.5	3	4	0.125	0.125	52	MA-430	Mark Andy	0.0625
1.5 x 1.75	2	4	0.125	0.125	120	6WR-309	650	0.125
1.5 x 2	3	3	0.125	0.125	51	MA-422	Mark Andy	0.125
1.5 x 2.1875	3	3	0.125	0.1875	57	MA-56	Mark Andy	RECTANGLE
1.5 x 2.25	2	3	0.125	0.125	114	6WR-177	650	0.125
1.5 x 2.5	3	3	0.125	0.125	63	MA-418	Mark Andy	0.125
1.5 x 2.75	3	3	0.125	0.125	138	WR-91	650	0.09375
1.5 x 2.875	4	2	0.125	0.125	96	WR-23	650	0.125
1.5 x 3	1	2	0	0.125	100	WR-51	650	0.125
1.5 x 3	4	2	0.125	0.125	50	MA-149	Mark Andy	RECTANGLE
1.5 x 3.125	3	2	0.125	0.125	104	6WR-234	650	0.125
1.5 X 3.25	2	2	0.125	0.125	108	WR-78-2	650	0.125
1.5 X 3.25	2	3	0.125	0.25	168	FLX-2	650	0.125
1.5 x 3.5	3	2	0.125	0.125	58	MA-140	Mark Andy	RECTANGLE
1.5 x 3.75	2	2	0.125	0.125	62	MA-22	Mark Andy	RECTANGLE
1.5 x 3.75	2	2	0.125	0.125	62	MA-231	Mark Andy	RECTANGLE
1.5 x 3.8	2	2	0.125	0.1375	126	WR-117	650	0.0625
1.5 x 3.8125	2	2	0.125	0.125	126	6WR-263	650	0.125
1.5 x 4	1	2	0	0.125	132	WR-68	650	0.125
1.5 x 4	2	2	0.125	0.125	66	MA-66	Mark Andy	RECTANGLE
1.5 x 4	2	2	0.125	0.125	66	MA-83	Mark Andy	RECTANGLE
1.5 x 4.125	2	2	0.125	0.125	68	MA-73	Mark Andy	RECTANGLE
1.5 x 4.1875	2	2	0.125	0.125	69	MA-227	Mark Andy	RECTANGLE
1.5 x 4.25	2	2	0.125	0.125	140	WR-103	650	0.125
1.5 x 4.5	2	2	0.125	0.125	74	MA-04	Mark Andy	RECTANGLE
1.5 x 4.625	4	2	0.125	0.125	76	MA-44	Mark Andy	RECTANGLE
1.5 x 4.625	2	2	0.125	0.125	76	MA-94	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
1.5 x 4.625	2	2	0.125	0.125	76	MA-203	Mark Andy	RECTANGLE
1.5 x 5	2	1	0.125	0.125	41	MA-132	Mark Andy	RECTANGLE
1.5 x 5.5	2	2	0.125	0.125	180	6WR-204	650	0.125
1.5 x 5.5	1	1	0	0.125	45	MA-20	Mark Andy	RECTANGLE
1.5 x 6.25	2	1	0.125	0.125	102	6WR-256	650	0.125
1.5 x 7	3	1	0.125	0.125	57	MA-45	Mark Andy	RECTANGLE
1.5 x 8.5	1	1	0	0.125	138	WR-109	650	0.0625
1.5 x 8.5	4	1	0.125	0.125	69	MA-273	Mark Andy	RECTANGLE
1.5 x 10	3	1	0.125	0.125	81	MA-436	Mark Andy	RECTANGLE
1.5625 x 1.7812	2	4	0.125	0.0625	118	6WR-323	650	0.0625
1.5625 x 2.4375	2	4	0.125	0.125	82	MA-575	Mark Andy	0.125
1.57 x 2.56	3	2	0.125	0.1275	86	6WR-307	650	0.125
1.5748 x 2.4409	2	4	0.125	0.0904	162	6WR-207	650	0.09375
1.6 x .375	3	21	0.125	0.125	84	FLX-56	Mark Andy	0.1875
1.6 x 1.52	2	5	0.125	0.13	132	6WR-285	650	0.125
1.62 x 4.81	2	2	0.125	0.1275	158	6WR-244	650	0.0625
1.625 x .78125	3	7	0.125	0.1295	51	MA-424	Mark Andy	0.125
1.625 x 1	4	9	0.125	0.125	81	FLX-71	10" M.A.	0.125
1.625 x 1.25	1	4	0	0.125	44	MA-111	Mark Andy	RECTANGLE
1.625 x 1.5	1	4	0	0.125	52	MA-09	Mark Andy	RECTANGLE
1.625 x 2	1	3	0	0.125	102	WR-31	650	0.125
1.625 x 3.5	2	2	0.125	0.125	116	6WR-252	650	0.125
1.625 x 3.5	3	2	0.125	0.125	58	MA-114	Mark Andy	RECTANGLE
1.625 x 3.75	2	2	0.125	0.125	124	WR-81	650	0.03125
1.625 x 4	2	2	0.125	0.125	132	6WR-276	650	0.125
1.625 x 4.5	2	2	0.125	0.125	74	MA-205	Mark Andy	RECTANGLE
1.625 x 4.5	2	2	0.125	0.125	74	MA-210	Mark Andy	RECTANGLE
1.625 x 4.625	2	2	0.125	0.125	76	MA-258	Mark Andy	RECTANGLE
1.625 x 4.625	2	2	0.125	0.125	76	MA-283	Mark Andy	RECTANGLE
1.625 x 4.75	4	2	0.125	0.125	78	PR-52	Propheteer	0.125
1.625 x 4.75	2	2	0.125	0.125	78	MA-92	Mark Andy	RECTANGLE
1.625 x 4.8125	2	2	0.125	0.125	79	MA-281	Mark Andy	RECTANGLE
1.625 x 5	2	1	0.125	0.125	82	MA-121	Mark Andy	RECTANGLE
1.625 x 5	2	1	0.125	0.125	41	MA-126	Mark Andy	RECTANGLE
1.625 x 5	2	2	0.125	0.125	164	6WR-259	650	0.125
1.625 x 5.125	3	2	0.125	0.125	84	MA-93	Mark Andy	RECTANGLE
1.625 x 5.25	2	1	0.125	0.125	43	MA-24	Mark Andy	RECTANGLE
1.625 x 6.125	2	1	0.125	0.125	50	MA-104	Mark Andy	RECTANGLE
1.625 x 6.125	2	1	0.125	0.125	50	MA-154	Mark Andy	RECTANGLE
1.625 x 6.25	1	1	0	0.125	102	6WR-267	650	0.125
1.625 x 6.25	2	1	0.125	0.125	51	MA-158	Mark Andy	RECTANGLE
1.625 x 7.75	2	1	0.125	0.125	63	MA-16	Mark Andy	RECTANGLE
1.625 x 8.375	1	1	0	0.125	136	WR-119	650	0.125
1.625 x 9	2	1	0.125	0.125	73	MA-17	Mark Andy	RECTANGLE
1.625 x 14	3	1	0.125	0.125	113	MA-564	Mark Andy	RECTANGLE
1.68 x 1.95	2	5	0.125	0.15	168	FLX-19	650	0.03125
1.6875 x 4	2	2	0.125	0.125	66	MA-70	Mark Andy	RECTANGLE
1.75 x .75	1	12	0.125	0.125	84	FLX-76	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
1.75 X 1	3	9	0.125	0.1667	168	FLX-12	650	0.125
1.75 x 1.4375	3	4	0.125	0.125	100	6WR-331	650	0.03125
1.75 x 1.75	2	4	0.125	0.125	120	6WR-197	650	0.125
1.75 x 2.25	2	3	0.125	0.125	114	6WR-210	650	0.125
1.75 x 2.5	1	3	0	0.125	126	WR-137	650	0.0312
1.75 x 2.5	2	2	0.125	0.125	42	MA-161	Mark Andy	RECTANGLE
1.75 X 3	1	3	0	0.125	150	WR-72	650	0.125
1.75 x 3	2	2	0.125	0.125	75	MA-373	Mark Andy	0.125
1.75 X 3.25	2	2	0.125	0.125	108	WR-95	650	0.0625
1.75 x 3.25	3	2	0.125	0.125	54	MA-145	Mark Andy	RECTANGLE
1.75 X 3.625	1	2	0	0.125	120	WR-131	650	0.125
1.75 x 3.625	2	2	0.125	0.125	60	MA-348	Mark Andy	RECTANGLE
1.75 X 4	3	2	0.125	0.125	132	WR-133	650	0.125
1.75 x 4	3	2	0.125	0.125	132	WR-134	650	0.125
1.75 x 4	4	2	0.125	0.125	66	MA10-45	10" M.A.	0.125
1.75 x 4.75	2	1	0.125	0.125	78	WR-86	650	0.125
1.75 x 5	2	3	0.125	0.125	164	6WR-248	650	0.125
1.75 x 5	3	2	0.125	0.125	82	PR-56	Propheteer	0.125
1.75 x 5	2	2	0.125	0.125	82	MA-05	Mark Andy	RECTANGLE
1.75 x 5.375	2	2	0.125	0.125	176	6WR-313	650	0.125
1.75 x 5.375	2	1	0.125	0.125	44	MA-108	Mark Andy	RECTANGLE
1.75 x 5.375	2	1	0.125	0.125	44	MA-162	Mark Andy	RECTANGLE
1.75 x 5.375	2	1	0.125	0.125	44	MA-172	Mark Andy	RECTANGLE
1.75 x 5.75	2	1	0.125	0.125	47	MA-174	Mark Andy	RECTANGLE
1.75 x 6.125	3	1	0.125	0.125	50	MA-35	Mark Andy	RECTANGLE
1.75 x 6.5	3	1	0.125	0.125	106	6WR-232	650	0.125
1.75 x 6.625	3	1	0.125	0.125	108	MA-257	Mark Andy	RECTANGLE
1.75 x 8	3	1	0.125	0.125	65	MA-337	Mark Andy	RECTANGLE
1.75 x 8	4	1	0.125	0.125	65	MA10-30	Mark Andy	0.125
1.75 x 8.75	3	1	0.125	0.125	71	MA-449	Mark Andy	squared
1.75 x 9.25	3	1	0.125	0.125	75	PR-87	Propheteer	0.125
1.75 x 9.375	5	1	0.125	0.125	76	PR-76	Propheteer	0.03125
1.75 x 11.5	2	1	0.125	0.125	93	MA-11	Mark Andy	RECTANGLE
1.8125 x 4.625	2	2	0.125	0.125	76	MA-72	Mark Andy	RECTANGLE
1.8125 x 6.5	2	1	0.125	0.125	53	MA-116	Mark Andy	RECTANGLE
1.85 x 3.97	1	2	0	0.155	132	6WR-205	650	0.125
1.875 x 2.125	2	3	0.125	0.125	108	6WR-334	650	0.125
1.875 x 2.25	1	3	0	0.125	57	MA-69	Mark Andy	RECTANGLE
1.875 x 2.25	2	3	0.125	0.125	57	MA-219	Mark Andy	RECTANGLE
1.875 x 2.5	1	3	0	0.125	126	WR-118	650	0.0625
1.875 x 2.5	2	3	0.125	0.125	126	6WR-238	650	0.125
1.875 x 3.375	2	2	0.125	0.125	112	WR-89	650	0.125
1.875 x 3.375	3	2	0.125	0.125	56	MA-260	Mark Andy	RECTANGLE
1.875 x 3.75	2	2	0.125	0.125	124	WR-94	650	0.0625
1.875 x 4.125	2	2	0.125	0.125	136	6WR-166	650	0.125
1.875 x 4.125	2	2	0.125	0.125	68	MA-202	Mark Andy	RECTANGLE
1.875 x 4.5	2	2	0.125	0.125	148	WR-97	650	0.125
1.875 x 4.75	2	2	0.125	0.125	78	MA-90	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
1.875 x 4.875	2	2	0.125	0.125	160	6WR-239	650	0.125
1.875 x 5	1	1	0	0.125	41	MA-34	Mark Andy	RECTANGLE
1.875 x 5.375	3	1	0.125	0.125	44	MA-276	Mark Andy	RECTANGLE
1.875 x 5.5	2	1	0.125	0.125	45	MA-259	Mark Andy	RECTANGLE
1.875 x 5.875	2	1	0.125	0.125	48	MA-124	Mark Andy	RECTANGLE
1.875 x 6.375	2	1	0.125	0.125	52	MA-165	Mark Andy	RECTANGLE
1.875 x 6.5	3	1	0.125	0.125	53	MA-169	Mark Andy	RECTANGLE
1.9688 x 9.25	3	1	0.125	0.125	75	MA-367	Mark Andy	squared
2 x .4	2	17	0.125	0.1221	71	PR-35	Propheteer	0.125
2 x .4	2	21	0.125	0.1	84	FLX-63	Mark Andy	0.125
2 x .625	2	8	0.125	0.125	96	6WR-196	650	0.125
2 x .75	1	12	0	0.125	168	FLX-50	650	0.0625
2 x .75	2	12	0.125	0.125	84	FLX-78	Mark Andy	RECTANGLE
2 x 1	3	6	0.125	0.125	54	MA-375	Mark Andy	0.125
2 x 1.125	2	8	0.125	0.1875	168	FLX-16	650	0.125
2 x 1.5	2	4	0.125	0.125	104	WR-142	650	0.0625
2 x 1.5	3	4	0.125	0.125	52	MA-139	Mark Andy	RECTANGLE
2 x 2	3	3	0.125	0.125	51	MA-483	Mark Andy	0.125
2 x 2.25	2	3	0.125	0.125	57	MA-41	Mark Andy	RECTANGLE
2 x 2.375	2	3	0.125	0.125	120	WR-8	650	0.125
2 x 2.625	2	2	0.125	0.125	44	MA-152	Mark Andy	RECTANGLE
2 x 2.75	2	2	0.125	0.125	92	WR-9	650	0.125
2 x 2.88	2	2	0.125	0.1825	98	6WR-296	650	0.125
2 x 3	2	2	0.125	0.125	100	6WR-198	650	0.125
2 x 3	3	3	0.125	0.125	75	MA-334	Mark Andy	0.125
2 x 3.25	2	2	0.125	0.125	108	6WR-185	650	0.125
2 x 3.25	3	3	0.125	0.125	81	PR-74	Propheteer	0.125
2 x 3.25	3	2	0.125	0.125	54	MA-263	Mark Andy	RECTANGLE
2 x 3.5	2	2	0.125	0.125	116	6WR-203	650	0.125
2 x 3.5	1	2	0	0.125	116	WR-70	650	0.0625
2 x 3.5	3	2	0.125	0.125	58	MA-184	Mark Andy	RECTANGLE
2 x 4	2	2	0.125	0.125	66	MA-420	Mark Andy	0.125
2 x 4	3	2	0.125	0.125	66	MA-397	Mark Andy	RECTANGLE
2 x 4	3	2	0.125	0.125	66	MA-467	Mark Andy	squared
2 x 4	2	2	0.125	0.125	66	MA-522	FOR FILM ONLY	0.125
2 x 4.25	1	2	0	0.125	70	MA-215	Mark Andy	RECTANGLE
2 x 4.5	2	2	0.125	0.125	74	MA-27	Mark Andy	RECTANGLE
2 x 5	2	2	0.125	0.125	164	6WR-246	650	0.125
2 x 5	2	1	0.125	0.125	41	MA-109	Mark Andy	RECTANGLE
2 x 5	1	1	0	0.125	41	MA-125	Mark Andy	RECTANGLE
2 x 5.25	2	2	0.125	0.125	172	6WR-258	650	0.125
2 x 5.5	2	1	0.125	0.125	90	6WR-187	650	0.125
2 x 5.5	1	1	0	0.125	45	MA-136	Mark Andy	RECTANGLE
2 x 5.5	2	1	0.125	0.125	45	MA-190	Mark Andy	RECTANGLE
2 x 5.5	2	1	0.125	0.125	45	MA-275	Mark Andy	RECTANGLE
2 x 5.625	2	1	0.125	0.125	92	6WR-184	650	0.125
2 x 5.625	3	2	0.125	0.125	92	MA-88	Mark Andy	RECTANGLE
2 x 5.75	2	1	0.125	0.125	94	6WR-266	650	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
2 x 5.75	2	1	0.125	0.125	47	MA-14	Mark Andy	RECTANGLE
2 x 5.875	2	1	0.125	0.125	96	WR-80	650	0.125
2 x 5.875	2	1	0.125	0.125	48	MA-21	Mark Andy	RECTANGLE
2 x 5.875	2	1	0.125	0.125	48	MA-155	Mark Andy	RECTANGLE
2 x 6	1	1	0	0.125	98	WR-121	650	0.125
2 x 6	3	2	0.125	0.125	98	MA-113	Mark Andy	RECTANGLE
2 x 6.5	2	1	0.125	0.125	53	MA-221	Mark Andy	RECTANGLE
2 x 7	2	1	0.125	0.125	57	MA-230	Mark Andy	RECTANGLE
2 x 7.25	2	1	0.125	0.125	59	MA-146	Mark Andy	RECTANGLE
2 x 7.875	2	1	0.125	0.125	128	WR-129	650	0.0625
2 x 8.25	2	1	0.125	0.125	67	MA-491	Mark Andy	0.125
2 x 8.5	2	1	0.125	0.125	69	MA-168	Mark Andy	RECTANGLE
2 x 11	4	1	0.125	0.125	89	PR-34	Propheteer	0.125
2 x 12	3	1	0.125	0.125	97	MA-605	Mark Andy	0.125
2 x 20	4	1	0.125	0.125	161	MA10-50	Mark Andy	0.125
2.04 x 3.35	2	3	0.125	0.15	168	FLX-15	650	0.125
2.0625 x .625	2	7	0.125	0.3393	54	MA-389	Mark Andy	squared
2.0625 x .5625	2	9	0.125	0.1458	51	MA-394	Mark Andy	RECTANGLE
2.0625 x 1.625	2	4	0.125	0.125	56	MA-133	Mark Andy	RECTANGLE
2.0625 x 6	2	1	0.125	0.125	49	MA-39	Mark Andy	RECTANGLE
2.0625 x 6	2	1	0.125	0.125	49	MA-278	Mark Andy	RECTANGLE
2.0625 x 9.5	3	1	0.125	0.125	77	MA-489	Mark Andy	squared
2.125 x 4	2	2	0.125	0.125	66	MA-50	Mark Andy	RECTANGLE
2.125 x 4.5	2	2	0.125	0.125	148	WR-11	650	0.125
2.125 x 4.5	2	2	0.125	0.125	74	MA-216	Mark Andy	RECTANGLE
2.125 x 5	2	1	0.125	0.125	41	MA-110	Mark Andy	RECTANGLE
2.125 x 5	1	1	0	0.125	41	MA-186	Mark Andy	RECTANGLE
2.125 x 5	2	2	0.125	0.125	82	MA-239	Mark Andy	RECTANGLE
2.125 x 5.875	2	1	0.125	0.125	48	MA-279	Mark Andy	RECTANGLE
2.125 x 6.25	2	1	0.125	0.125	51	MA-195	Mark Andy	RECTANGLE
2.125 x 6.5	2	1	0.125	0.125	53	MA-115	Mark Andy	RECTANGLE
2.125 x 7	2	1	0.125	0.125	57	MA-223	Mark Andy	RECTANGLE
2.125 x 7.75	2	1	0.125	0.125	63	MA-187	Mark Andy	RECTANGLE
2.125 x 9	2	1	0.125	0.125	146	WR-160	650	0.3125
2.125 x 9	4	1	0.125	0.125	73	MA10-68	Mark Andy	0.3125
2.1875 x 2.875	2	2	0.125	0.125	48	MA-188	Mark Andy	RECTANGLE
2.1875 x 5.75	1	1	0	0.125	47	MA-175	Mark Andy	RECTANGLE
2.1875 x 5.75	2	1	0.125	0.125	47	MA-226	Mark Andy	RECTANGLE
2.2 x 1.32	2	5	0.125	0.13	116	6WR-286	650	0.125
2.246 x 1.437	1	4	0	0.1255	50	MA-498	Mark Andy	0.125
2.25 x 1	2	5	0.25	0.125	90	WR-69	650	0.125
2.25 x 1.5	2	4	0.125	0.0625	100	WR-150	650	0.0625
2.25 x 1.5625	1	4	0	0.125	108	6WR-268	650	0.125
2.25 x 1.5625	2	5	0.125	0.0625	130	WR-82	650	0.125
2.25 x 1.875	1	3	0	0.125	48	MA-106	Mark Andy	RECTANGLE
2.25 x 2	2	5	0.125	0.1	168	FLX-47	650	0.125
2.25 x 2.25	1	3	0	0.125	57	MA-32	Mark Andy	RECTANGLE
2.25 x 2.5	2	3	0.125	0.125	63	MA-482	Mark Andy	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
2.25 x 2.625	1	2	0	0.125	44	MA-107	Mark Andy	RECTANGLE
2.25 x 3	1	2	0	0.125	100	6WR-170	650	0.25
2.25 x 3	2	2	0.125	0.125	100	6WR-327	650	0.125
2.25 x 3	2	2	0.125	0.25	52	MA-593	Mark Andy	0.125
2.25 x 3.25	1	2	0	0.25	112	WR-163	650	0.125
2.25 x 3.25	2	2	0.125	0.125	108	6WR-192	650	0.125
2.25 x 3.25	2	2	0.125	0.125	108	WR-38	650	0.125
2.25 x 3.75	1	2	0	0.125	124	WR-92	650	0.0625
2.25 x 3.75	2	2	0.125	0.125	62	MA-60	Mark Andy	RECTANGLE
2.25 x 4	2	2	0.125	0.125	132	6WR-279	650	0.125
2.25 x 4	2	2	0.125	0.125	66	MA-47	Mark Andy	RECTANGLE
2.25 x 4.125	1	2	0	0.125	68	MA-77	Mark Andy	RECTANGLE
2.25 x 4.5	2	2	0.125	0.125	148	WR-12	650	0.125
2.25 x 4.5	2	2	0.125	0.125	74	MA-36	Mark Andy	RECTANGLE
2.25 x 5	2	1	0.125	0.125	82	WR-98	650	0.0625
2.25 x 5.25	2	1	0.125	0.125	43	MA-103	Mark Andy	RECTANGLE
2.25 x 5.5	2	1	0.125	0.125	90	WR-138	650	0.0312
2.25 x 5.5	2	1	0.125	0.125	45	MA-18	Mark Andy	RECTANGLE
2.25 x 6	2	1	0.125	0.125	49	MA-74	Mark Andy	RECTANGLE
2.25 x 6.25	2	1	0.125	0.125	102	6WR-54	650	0.0625
2.25 x 6.25	2	1	0.125	0.125	51	MA-185	Mark Andy	RECTANGLE
2.25 x 6.375	2	1	0.125	0.125	52	MA-198	Mark Andy	RECTANGLE
2.25 x 6.5	1	1	0	0.125	106	WR-114	650	0.125
2.25 x 6.75	1	1	0.125	0.125	55	MA-49	Mark Andy	RECTANGLE
2.25 x 6.75	2	1	0.125	0.125	55	MA-233	Mark Andy	RECTANGLE
2.25 x 6.875	2	1	0.125	0.125	112	6WR-326	650	0.125
2.25 x 13.25	3	1	0.125	0.125	107	PR-67	Propheteer	0.125
2.2834 x 2.3622	2	3	0.125	0.0961	59	MA-445	Mark Andy	0.125
2.3125 x 4.125	2	2	0.125	0.125	68	MA-65	Mark Andy	RECTANGLE
2.36 x 4	2	2	0.125	0.125	66	MA-556	Mark Andy	RECTANGLE
2.375 X .625	2	14	0.125	0.125	168	FLX-10	650	0.125
2.375 x .875	2	8	0.25	0.2813	148	WR-132	650	0.125
2.375 x 1.5625	2	4	0.125	Butted	100	WR-43	650	squared
2.375 x 2	2	3	0.125	0.125	51	MA-181	Mark Andy	RECTANGLE
2.375 x 2.75	2	2	0.125	0.125	46	MA-156	Mark Andy	RECTANGLE
2.375 x 3.75	2	2	0.125	0.125	62	MA-339	Mark Andy	RECTANGLE
2.375 x 4.25	1	2	0	0.125	70	MA-213	Mark Andy	RECTANGLE
2.375 x 4.625	2	2	0.125	0.125	76	MA-85	Mark Andy	RECTANGLE
2.375 x 4.625	1	2	0	0.125	76	MA-97	Mark Andy	RECTANGLE
2.375 x 6	2	1	0.125	0.125	49	MA-164	Mark Andy	RECTANGLE
2.375 x 6.25	2	1	0.125	0.125	51	MA-147	Mark Andy	RECTANGLE
2.375 x 6.375	2	1	0.125	0.125	52	MA-144	Mark Andy	RECTANGLE
2.375 x 6.875	1	1	0	0.125	56	MA-141	Mark Andy	RECTANGLE
2.375 x 11.5	1	1	0	0.125	93	PR-64	Propheteer	0.125
2.4375 x 5.9375	1	1	0.125	0.1875	98	6WR-318	650	0.125
2.5 x .5	1	10	0	0.125	100	WR-48	650	0.015625
2.5 x .75	2	12	0.125	0.125	168	FLX-48	650	0.125
2.5 x 1	2	6	0.125	0.125	54	MA-354	Mark Andy	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
2.5 x 1	2	6	0.125	0.125	54	MA-325	Mark Andy	0.03125
2.5 x 1.375	2	5	0.125	0.125	60	MA-453	Mark Andy	0.125
2.5 x 1.5	2	4	0.125	0.125	52	MA-487	Mark Andy	0.125
2.5 x 1.65625	2	4	0.125	0.3125	126	WR-39	650	0.09375
2.5 x 1.75	2	4	0.125	0.125	120	6WR-182	650	0.125
2.5 x 1.75	1	3	0.125	0.125	45	MA-192	Mark Andy	RECTANGLE
2.5 x 14.5	1	1	0	0.125	117	PR-71	Propheteer	0.125
2.5 x 2	2	3	0.125	0.125	51	MA-409	Mark Andy	0.125
2.5 x 2.5	1	3	0	0.125	126	WS-6	650	0.0625
2.5 x 2.5	2	3	0.125	0.125	63	MA-464	Mark Andy	0.0625
2.5 x 2.6875	2	4	0.125	0.125	90	MA-594	Mark Andy	0.125
2.5 x 3	2	2	0.125	0.125	100	6WR-169A	650	0.125
2.5 x 3	2	2	0.125	0.125	100	6WR-169	650	0.125
2.5 x 3	3	3	0.125	0.125	75	PR-72	Propheteer	0.125
2.5 x 3.125	1	2	0	0.125	52	MA-08	Mark Andy	RECTANGLE
2.5 X 3.1875	2	3	0.125	0.3125	168	FLX-7	650	0.125
2.5 x 3.375	1	2	0	0.125	56	MA-82	Mark Andy	RECTANGLE
2.5 x 3.375	2	2	0.125	0.125	56	MA-218	Mark Andy	RECTANGLE
2.5 x 3.5	2	2	0.125	0.125	58	MA-37	Mark Andy	RECTANGLE
2.5 x 3.875	3	2	0.125	0.125	64	PR-28	Propheteer	0.125
2.5 x 4	1	2	0	0.125	132	6WR-254	650	0.125
2.5 x 4.1875	2	2	0.125	0.125	138	6WR-176	650	0.125
2.5 x 4.5	2	2	0.125	0.125	148	WR-145	650	0.125
2.5 x 4.5	2	2	0.125	0.125	74	MA-217	Mark Andy	RECTANGLE
2.5 x 4.625	1	2	0	0.125	152	WR-90	650	0.0625
2.5 x 4.75	2	2	0.125	0.125	78	PR-36	Propheteer	0.125
2.5 x 5	2	1	0.125	0.125	82	6WR-172	650	0.125
2.5 x 5	2	2	0.125	0.125	82	MA-87	Mark Andy	RECTANGLE
2.5 x 5	2	2	0.125	0.125	82	MA-95	Mark Andy	RECTANGLE
2.5 x 5.25	2	1	0.125	0.125	43	MA-127	Mark Andy	RECTANGLE
2.5 x 5.5	2	2	0.125	0.125	90	MA-242	Mark Andy	RECTANGLE
2.5 x 5.875	2	1	0.125	0.125	48	MA-25	Mark Andy	RECTANGLE
2.5 x 6	2	1	0.125	0.125	98	6WR-257	650	0.125
2.5 x 6	2	2	0.125	0.125	98	PR-58	Propheteer	0.125
2.5 x 6	2	1	0.125	0.125	49	MA-105	Mark Andy	RECTANGLE
2.5 x 6.25	2	2	0.125	0.125	102	PR-84	Propheteer	0.125
2.5 x 6.25	2	1	0.125	0.125	51	MA-151	Mark Andy	RECTANGLE
2.5 x 6.5	2	1	0.125	0.125	53	MA-183	Mark Andy	0.125
2.5 x 6.5	2	1	0.125	0.125	106	6WR-328	650	squared
2.5 x 6.75	2	1	0.125	0.125	110	6WR-235	650	0.125
2.5 x 6.875	2	1	0	0.125	56	MA-256	Mark Andy	RECTANGLE
2.5 x 6.875	2	1	0.125	0.125	56	MA-54	Mark Andy	RECTANGLE
2.5 x 7	2	1	0.125	0.125	114	6WR-227	650	0.125
2.5 x 7.25	2	1	0.125	0.125	59	MA-28	Mark Andy	RECTANGLE
2.5 x 7.5	2	1	0.125	0.125	61	MA-166	Mark Andy	RECTANGLE
2.5 x 7.5	2	1	0.125	0.125	61	MA-277	Mark Andy	RECTANGLE
2.5 x 8	2	1	0.125	0.125	65	PR-66	Propheteer	0.125
2.5 x 8	2	1	0.125	0.125	65	MA-224	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
2.5 x 8.25	1	1	0	0.125	67	MA-64	Mark Andy	RECTANGLE
2.5 x 8.25	2	1	0.125	0.125	67	MA-67	Mark Andy	RECTANGLE
2.5 x 9	3	1	0.125	0.125	73	PR-19	Propheteer	0.125
2.5 x 9	2	1	0.125	0.125	73	MA-272	Mark Andy	RECTANGLE
2.5 x 9.25	2	1	0.125	0.125	75	MA-366	Mark Andy	0.125
2.5 x 9.5	2	1	0.125	0.125	77	MA-369	Mark Andy	RECTANGLE
2.5 x 10.25	2	1	0.125	0.25	84	MA-450	Mark Andy	squared
2.55 x .375	2	21	0.125	0.125	84	FLX-57	Mark Andy	0.1875
2.56 x 1.35	2	5	0.125	0.15	60	MA-469	Mark Andy	0.1
2.61 x .830	2	8	0.125	0.1231	61	MA-455	Mark Andy	0.125
2.625 x .625	1	13	0	0.125	78	FLX-77	Mark Andy	RECTANGLE
2.625 x 1.4375	2	4	0.125	0.125	100	WR-55	650	0.125
2.625 x 2.625	2	3	0.125	0.125	132	6WR-312	650	0.125
2.625 x 2.75	2	3	0.125	0.125	69	PR-1	Propheteer	0.1875
2.625 x 4	2	2	0.125	0.125	66	MA-53	Mark Andy	RECTANGLE
2.625 x 4.125	2	2	0.125	0.125	136	WR-139	650	0.0625
2.625 x 4.5	2	2	0.125	0.125	74	MA-555	Mark Andy	0.0625
2.625 x 6.0625	2	2	0.125	0.125	99	MA-284	Mark Andy	
2.625 x 6.0625	2	2	0.125	0.125	99	MA-285	Mark Andy	
2.625 x 6.125	2	1	0.125	0.125	100	WR-144	650	0.125
2.625 x 6.125	2	1	0.125	0.125	50	MA-255	Mark Andy	RECTANGLE
2.625 x 7	3	1	0.125	0.125	114	PR-77	Propheteer	0.125
2.625 x 7	1	1	0	0.125	57	MA-23	Mark Andy	RECTANGLE
2.625 x 7	2	1	0.125	0.125	57	MA-55	Mark Andy	RECTANGLE
2.625 x 7.5	1	1	0	0.125	122	WR-113	650	0.09375
2.625 x 9	2	1	0.125	0.125	146	WR-110	650	0.125
2.6875 x 2.5	2	4	0.125	0.125	84	FLX-75	Mark Andy	RECTANGLE
2.6875 x 4.1875	2	2	0.125	0.125	69	MA-86	Mark Andy	RECTANGLE
2.6875 x 4.25	2	2	0.125	0.125	70	MA-208	Mark Andy	RECTANGLE
2.75 x 1.5	2	4	0.125	0.125	52	MA-554	Mark Andy	0.125
2.75 x 1.75	2	4	0.125	0.125	120	6WR-290	650	0.125
2.75 x 1.75	3	5	0.125	0.125	75	PR-68	Propheteer	0.03125
2.75 x 2	2	3	0.125	0.125	51	MA-428	Mark Andy	0.125
2.75 x 2.25	2	3	0.125	0.125	57	MA-535	Mark Andy	0.125
2.75 x 2.75	2	3	0.125	0.125	138	6WR-220	650	0.125
2.75 X 2.75	3	3	0.125	0.125	69	PR-81	Propheteer	0.125
2.75 x 2.75	2	2	0.125	0.125	46	MA-130	Mark Andy	RECTANGLE
2.75 x 3	2	2	0.125	0.125	100	6WR-171	650	0.125
2.75 x 3.25	2	2	0.125	0.125	108	6WR-299	650	0.125
2.75 x 3.375	3	3	0.125	0.125	84	MA10-58	10" M.A.	0.125
2.75 x 4.75	3	2	0.125	0.125	78	PR-27	Propheteer	0.125
2.75 x 5.5	2	1	0.125	0.125	45	MA-177	Mark Andy	RECTANGLE
2.75 x 5.75	2	1	0.125	0.125	94	WR-140	650	0.03125
2.75 x 6	2	1	0.125	0.125	49	MA-26	Mark Andy	RECTANGLE
2.75 x 7.25	2	1	0.125	0.125	59	MA-222	Mark Andy	RECTANGLE
2.75 x 8	1	1	0	0.125	130	WR-88	650	0.0625
2.75 x 8.25	3	1	0.125	0.125	67	PR-89	Propheteer	0.125
2.75 x 10	2	1	0.125	0.125	162	6WR-245	650	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
2.875 x 3.75	1	2	0	0.125	124	6WR-265	650	0.125
2.875 x 5.8125	2	1	0.125	0.125	95	WR-13	650	0.09375
2.875 x 6.125	1	1	0	0.125	50	MA-170	Mark Andy	RECTANGLE
2.875 x 6.125	2	2	0.125	0.125	100	MA-586	Mark Andy	0.125
2.875 x 6.5	2	1	0.125	0.125	53	MA-196	Mark Andy	RECTANGLE
2.875 x 6.875	2	1	0.125	0.125	56	MA-68	Mark Andy	RECTANGLE
2.875 x 6.875	1	1	0	0.125	56	MA-76	Mark Andy	RECTANGLE
2.875 x 7	2	2	0.125	0.125	114	PR-53	Propheteer	0.125
2.875 x 9.5	1	1	0	0.125	77	MA-96	Mark Andy	RECTANGLE
2.88 x 2	2	3	0.125	0.125	102	6WR-287	650	0.125
2.9375 x 9.5	3	1	0.125	0.25	78	MA10-09	Mark Andy	squared
3 x .625	1	8	0	0.125	96	6WR-222	650	0.125
3 x 1	2	6	0.125	0.125	54	MA-460	Mark Andy	0.125
3 x 1	2	7	0.125	0.125	63	PR-6	Propheteer	0.09375
3 x 1.25	2	5	0.125	0.125	55	MA-413	Mark Andy	0.125
3 x 1.5	2	4	0.125	0.125	52	MA-371	Mark Andy	0.125
3 x 1.5	2	5	0.125	0.125	65	PR-12	Propheteer	0.125
3 x 1.625	2	4	0.125	Butted	104	WR-41	650	0.09375
3 x 1.75	1	4	0	0.125	120	WR-66	650	0.125
3 x 1.75	2	4	0.125	0.125	120	6WR-195	650	0.125
3 x 1.75	1	5	0.125	0.125	75	PR-91	Tri-Media only	0.125
3 x 2	1	3	0	0.125	102	6WR-183	650	0.125
3 x 2	2	4	0.125	0.125	68	PR-10	Propheteer	0.125
3 x 2	3	4	0.125	0.125	68	PR-10B	Propheteer	0.125
3 x 2	3	4	0.125	0.125	68	PR-10C	10" M.A.	0.125
3 x 2	2	4	0.125	0.125	68	MA-406	Mark Andy	0.125
3 x 2.5	1	4	0	0.125	168	FLX-38	650	0.125
3 x 2.5	2	4	0.125	0.125	84	PR-22	Propheteer	0.125
3 x 3	2	2	0.125	0.125	50	MA-365	Mark Andy	0.125
3 x 3	2	3	0.125	0.125	75	MA-545	Mark Andy	0.125
3 x 3	2	3	0.125	0.125	75	PR-85	Propheteer	0.125
3 x 3.5	2	3	0.125	0.125	87	PR-63	Propheteer	0.125
3 x 3.5	2	3	0.125	0.125	87	MA-559	Mark Andy	0.125
3 x 3.5	1	2	0	0.125	116	6WR-330	650	0.125
3 x 3.875	1	2	0	0.125	64	MA-78	Mark Andy	RECTANGLE
3 x 4	2	2	0.125	0.125	66	PR-62	Propheteer	0.125
3 x 4	1	2	0	0.125	132	WR-15	650	0.125
3 x 4	2	2	0.125	0.125	66	MA-252	Mark Andy	RECTANGLE
3 x 4.25	2	2	0.125	0.125	70	MA-385	Mark Andy	0.125
3 x 4.875	1	1	0	0.125	80	MA-91	Mark Andy	RECTANGLE
3 x 4.875	2	2	0.125	0.125	80	MA-241	Mark Andy	RECTANGLE
3 x 5	2	2	0.125	0.125	164	6WR-229	650	0.125
3 x 5	1	3	0	0.125	164	6WR-301	650	squared
3 x 5	3	2	0.125	0.125	82	PR-20	Propheteer	0.125
3 x 5	2	2	0.125	0.125	82	PR-70	Propheteer	0.125
3 x 5	1	2	0	0.125	164	WR-135	650	0.03125
3 x 5	2	2	0.125	0.125	82	MA-150	Mark Andy	RECTANGLE
3 x 5	1	1	0	0.125	41	MA-173	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
3 x 5.5	2	2	0.125	0.125	90	MA-328	Mark Andy	0.125
3 x 6	2	1	0.125	0.125	98	WR-157	650	0.125
3 x 6	1	1	0	0.125	49	MA-101	Mark Andy	RECTANGLE
3 x 6	2	1	0.125	0.125	49	MA-194	Mark Andy	RECTANGLE
3 x 7	2	1	0.125	0.125	57	MA-434	Mark Andy	0.125
3 x 7	2	2	0.125	0.125	114	PR-55	Propheteer	0.125
3 x 7.5	1	1	0	0.125	122	WR-42-7	650	0.125
3 x 7.5	2	1	0.125	0.125	122	6WR-316	650	0.125
3 x 8	2	1	0.125	0.125	65	MA-236	Mark Andy	RECTANGLE
3 x 8.125	1	1	0	0.125	132	6WR-278	650	0.125
3 x 8.25	2	1	0.125	0.125	67	MA-237	Mark Andy	RECTANGLE
3 x 8.25	2	1	0.125	0.125	67	MA-282	Mark Andy	RECTANGLE
3 x 8.5	3	1	0.125	0.125	69	PR-26	Propheteer	0.125
3 x 8.625	2	1	0.125	0.125	70	MA-200	Mark Andy	RECTANGLE
3 x 9	2	1	0.125	0.125	146	6WR-249	650	0.125
3 x 9.5	1	1	0	0.125	77	MA-138	Mark Andy	RECTANGLE
3 x 9.5	2	1	0.125	0.125	77	MA-443	Mark Andy	RECTANGLE
3 x 10	2	1	0.125	0.125	81	MA-529	Mark Andy	0.125
3 x 11.75	3	1	0.125	0.125	95	PR-92	Propheteer	0.125
3 x 12.75	3	1	0.125	0.125	103	PR-9	Propheteer	0.125
3.0312 x 9.5	2	1	0.125	0.25	78	MA10-16	Mark Andy	squared
3.0312 x 12.9375	2	1	0.125	0.9375	105	MA10-44	Mark Andy	squared
3.125 x 2.25	2	4	0.125	0.125	76	PR-30	Propheteer	0.125
3.125 x 4	2	2	0.125	0.125	66	PR-59	Propheteer	0.125
3.125 x 4.25	1	2	0	0.125	140	6WR-298	650	0.125
3.125 x 6.125	2	1	0.125	0.125	50	MA-137	Mark Andy	RECTANGLE
3.125 x 6.75	1	1	0	0.125	55	MA-38	Mark Andy	RECTANGLE
3.125 x 10.5	2	1	0.125	0.125	85	PR-88	Propheteer	0.125
3.125 x 12.935	2	1	0.125	0.19	105	MA10-47	10" M.A.	squared
3.1875 x 8	2	1	0.125	0.125	65	MA-274	Mark Andy	RECTANGLE
3.1875 x 10.25	2	1	0.125	0.25	84	MA-485	Mark Andy	0.3125
3.25 x 2.25	2	4	0.125	0.125	76	PR-37	Propheteer	0.125
3.25 x 2.5	1	4	0	0.125	168	FLX-53	650	0.125
3.25 x 2.5	2	4	0.125	0.125	84	FLX-62	Mark Andy	0.125
3.25 x 2.5	2	3	0.125	0.25	66	MA10-22	10" M.A.	0.125
3.25 x 3	1	2	0	0.125	100	WR-14	650	0.125
3.25 x 3.25	2	2	0.125	0.125	54	MA-234	Mark Andy	RECTANGLE
3.25 x 3.375	2	3	0.125	0.125	84	PR-2	Propheteer	0.125
3.25 x 4	2	2	0.125	0.125	66	MA10-11	Mark Andy	0.125
3.25 x 4.5625	1	2	0	0.125	150	6WR-311	650	0.0625
3.25 x 5	1	2	0	0.125	164	WR-102	650	0.125
3.25 x 5.5	1	2	0	0.125	90	MA-433	Mark Andy	RECTANGLE
3.25 x 7	2	1	0.125	0.125	57	MA-179	Mark Andy	RECTANGLE
3.25 x 7.5	1	1	0	0.125	61	MA-31	Mark Andy	RECTANGLE
3.25 x 8.25	1	1	0	0.125	67	MA-100	Mark Andy	RECTANGLE
3.25 x 8.25	2	1	0.125	0.125	67	MA-189	Mark Andy	RECTANGLE
3.25 x 8.625	1	1	0.125	0.125	70	MA-254	Mark Andy	RECTANGLE
3.375 x 1.125	1	6	0	0.125	60	MA-15	Mark Andy	RECTANGLE

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
3.375 x 3.25	2	3	0.125	0.125	81	PR-51	Propheteer	0.125
3.375 x 5	1	1	0	0.125	41	MA-134	Mark Andy	RECTANGLE
3.375 x 10.5	2	1	0.125	0.125	85	PR-57	Propheteer	0.125
3.375 x 11.875	2	1	0.125	0.125	96	PR-43	Propheteer	0.125
3.375 x 11.875	1	1	0	0.125	192	WR-152	650	0.125
3.375 x 16	1	1	0	0.125	129	MA-530	Mark Andy	0.125
3.5 x .5	1	15	0	0.15	78	FLX-73	Mark Andy	RECTANGLE
3.5 x 1	1	5	0	0.125	90	6WR-300	650	0.125
3.5 x 1.5	1	4	0	0.125	104	6WR-282	650	0.125
3.5 x 2	2	4	0.125	0.125	68	PR-13	Propheteer	0.125
3.5 x 2.125	1	3	0	0.125	108	6WR-175	650	0.125
3.5 x 2.25	1	4	0	0.125	152	WR-106	650	0.09375
3.5 x 2.5	1	3	0.125	0.125	63	MA-527	Mark Andy	0.125
3.5 x 2.5	2	3	0.125	0.125	63	PR-15	Propheteer	0.125
3.5 x 3	2	3	0.125	0.125	75	PR-21	Propheteer	0.125
3.5 x 3.125	1	2	0	0.125	104	WR-16	650	0.125
3.5 x 3.5	2	3	0.125	0.125	87	PR-31	Propheteer	0.0625
3.5 x 4.5	1	2	0	0.125	74	MA-410	Mark Andy	0.125
3.5 x 5	2	2	0.125	0.125	82	PR-82	Propheteer	0.125
3.5 x 5	1	1	0	0.125	41	MA-118	Mark Andy	RECTANGLE
3.5 x 5.125	1	2	0	0.125	168	6WR-297	650	0.125
3.5 x 5.25	2	2	0.125	0.125	86	PR-17	Propheteer	0.125
3.5 x 5.25	2	2	0.125	0.125	86	PR-17B	10" M.A.	0.125
3.5 x 6	1	1	0	0.125	49	MA-492	Mark Andy	0.125
3.5 x 6.75	1	1	0	0.125	110	6WR-292	650	0.125
3.5 x 7.5	1	1	0	0.125	61	MA-43	Mark Andy	RECTANGLE
3.5 x 7.875	2	1	0.125	0.125	64	PR-46	Propheteer	0.125
3.5 x 8	1	1	0	0.125	130	6WSP-87	650	squared
3.5 x 8	2	1	0.125	0.125	65	PR-33	Propheteer	0.125
3.5 x 8	1	1	0	0.125	65	MA-98	Mark Andy	RECTANGLE
3.5 x 8.5	1	1	0	0.125	138	WR-143	650	0.125
3.5 x 8.5	2	1	0.125	0.125	69	MA10-31	10" M.A.	0.125
3.5 x 8.5	2	1	0.125	0.125	69	MA10-31B	10" M.A.	0.125
3.5 X 13.75	2	1	0.125	0.125	111	PR-78	Propheteer	0.125
3.5 x 15.375	2	1	0.125	0.125	124	MA10-10	Mark Andy	squared
3.625 x 1.75	1	4	0.125	0.125	120	6WR-317	650	0.125
3.625 x 4.25	1	2	0	0.125	70	MA-207	Mark Andy	RECTANGLE
3.625 x 5.5	1	2	0	0.125	90	MA-153	Mark Andy	RECTANGLE
3.625 x 7.875	1	1	0	0.125	64	MA-58	Mark Andy	RECTANGLE
3.625 x 13	1	1	0	0.125	105	MA-238	Mark Andy	RECTANGLE
3.75 x .625	1	9	0	0.125	108	6WR-274	650	0.125
3.75 x 1.5	1	6	0	0.125	78	FLX-69	Mark Andy	0.125
3.75 x 2.5	2	3	0.125	0.125	63	MA10-55	10" M.A.	0.125
3.75 x 3	1	2	0	0.0125	100	6WR-302	650	0.125
3.75 x 6.25	1	1	0	0.125	51	MA-120	Mark Andy	RECTANGLE
3.75 x 6.375	1	1	0	0.125	104	WR-84	650	0.125
3.75 x 8.5	1	1	0	0.125	69	MA-07	Mark Andy	RECTANGLE
3.875 x 2.125	2	4	0.125	0.125	72	PR-32	Propheteer	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
3.875 x 2.125	2	4	0.125	0.125	72	PR-49	Propheteer	0.125
3.875 x 4.75	1	2	0	0.125	156	6WR-305	650	0.125
3.875 x 5.125	2	2	0.125	0.125	84	MA10-41	Mark Andy	0.21875
4 x .94	1	5	0	0.135	86	WR-28	650	0.0625
4 x 1	1	6	0	0.25	120	6WR-322	650	0.125
4 x 1.375	1	5	0	0.125	60	MA-454	Mark Andy	0.125
4 x 1.5	1	4	0	0.125	104	WR-67	650	0.09375
4 x 1.5	1	5	0	0.125	65	MA-502	Mark Andy	0.125
4 x 1.5	1	5	0	0.125	130	WR-115	650	0.125
4 x 1.625	1	4	0	0.125	112	6WR-225	650	0.125
4 x 1.625	1	4	0	0.125	56	MA-468	Mark Andy	squared
4 x 1.625	1	4	0	0.125	56	MA-521	FOR FILM ONLY	0.125
4 x 1.75	1	4	0	0.125	60	MA-376	Mark Andy	0.125
4 x 1.9375	2	6	0.125	0.125	99	MA10-59	10" M.A.	0.125
4 x 1.9375	2	4	0.125	0.125	66	PR-18A	Propheteer	0.125
4 x 1.9375	2	4	0.125	0.125	66	PR-18B	Propheteer	0.125
4 x 1.9375	1	3	0	0.0625	96	WR-123	650	0.0938
4 x 2	1	3	0	0.125	51	MA-571	Mark Andy	0.125
4 x 2.375	1	3	0	0.125	60	MA-604	Mark Andy	0.125
4 x 2.5	1	3	0	0.125	126	6WR-202	650	0.125
4 x 2.5	2	4	0.125	0.125	84	PR-50	Propheteer	0.125
4 x 2.75	1	3	0	0.125	69	MA-465	Mark Andy	0.125
4 x 3	2	3	0.125	0.125	75	PR-24	Propheteer	0.125
4 x 3	2	3	0.125	0.125	75	PR-24B	Propheteer	0.125
4 x 3	1	3	0	0.125	75	MA-542	Mark Andy	0.125
4 x 3.125	2	3	0.125	0.125	78	PR-60	Propheteer	0.125
4 x 3.25	1	2	0	0.125	54	MA-582	Mark Andy	0.125
4 x 3.5	1	2	0	0.125	116	WR-146	650	0.125
4 x 3.5	2	3	0.125	0.125	87	MA10-32	10" M.A.	0.125
4 x 4	2	2	0.125	0.125	66	PR-16	Propheteer	0.125
4 x 4	2	2	0.125	0.125	66	PR-16B	10" M.A.	0.125
4 x 4	1	2	0	0.125	132	WS-3	650	0.125
4 x 4	1	2	0	0.125	66	MA-479	Mark Andy	0.125
4 x 4.4375	1	1	0	0.125	73	MA-212	Mark Andy	RECTANGLE
4 x 5	2	2	0.125	0.125	82	PR-5	Propheteer	0.125
4 x 5	1	2	0	0.125	164	WR-105	650	0.125
4 x 6	1	1	0	0.25	100	6WR-154	650	0.125
4 x 6	1	1	0	0.125	49	MA-323	Mark Andy	0.125
4 x 6	2	2	0.125	0.125	98	PR-41	Propheteer	0.125
4 x 6	1	1	0	0.125	98	6WR-262	FOR FILM ONLY	0.125
4 x 6.25	1	1	0	0.125	102	6WR-280	650	0.125
4 x 6.25	2	2	0.125	0.125	102	MA10-12	Mark Andy	0.125
4 x 6.5	1	1	0	0.125	106	WR-130	650	0.031
4 x 6.5	2	2	0.125	0.125	106	MA10-46	10" M.A.	0.125
4 x 7	2	2	0.125	0.125	114	PR-25	Propheteer	0.125
4 x 7	1	1	0	0.125	114	WR-100	650	0.125
4 x 7	1	1	0	0.125	57	MA-33	Mark Andy	RECTANGLE
4 x 8	1	1	0	0.125	130	WR-155	650	0.125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
4 x 8	1	1	0	0.125	130	6WR-199	650	squared
4 x 8	2	1	0.125	0.125	65	PR-86	Propheteer	0.125
4 x 8.5	2	1	0.125	0.125	69	PR-45	Propheteer	0.125
4 x 9	2	1	0	0.125	73	PR-23	Propheteer	0.125
4 x 11	1	1	0	0.125	178	6WR-291	650	0.125
4 x 12	2	1	0.125	0.125	97	PR-90	Propheteer	0.125
4 x 13.5	1	1	0	0.125	109	MA-301	Mark Andy	RECTANGLE
4.125 x 2.125	1	3	0	0.125	108	6WR-104	650	0.0625
4.125 x 2.375	2	4	0.125	0.125	80	PR-83	Propheteer	0.125
4.125 x 5.3125	1	1	0	0.1875	88	6WR-253	650	0.0312
4.170 x 9.5	2	1	0.125	0.25	78	MA10-28	10" M.A.	RECTANGLE
4.1875 x 5.5	1	1	0	0.125	45	MA-176	Mark Andy	RECTANGLE
4.1875 x 9.5	2	1	0.125	0.25	78	MA10-27	10" M.A.	RECTANGLE
4.25 x 1	1	8	0	0.125	72	PR-44	Propheteer	0.125
4.25 x 2	1	3	0	0.125	102	WR-18	650	0.125
4.25 x 2.5	1	2	0	0.125	84	WR-96	650	0.25
4.25 x 2.75	1	3	0	0.125	138	6WR-332	650	0.125
4.25 x 6.25	2	2	0.125	0.125	102	PR-29	Propheteer	0.125
4.25 x 9.75	1	1	0	0.125	79	MA-57	Mark Andy	RECTANGLE
4.25 x 12.75	1	1	0	0.125	103	PR-61	Propheteer	0.125
4.5 x .5	1	16	0	0.1563	84	FLX-55	Mark Andy	0.0625
4.5 x .75	1	10	0	0.125	70	PR-38	Propheteer	0.125
4.5 x .75	1	12	0	0.125	84	FLX-61	Mark Andy	0.125
4.5 x 2.5	1	2	0	0.125	84	WR-125	650	0.125
4.5 x 2.5	2	3	0.125	0.125	63	MA10-49	10" M.A.	0.125
4.5 x 3	1	3	0	0.125	150	WR-120	650	0.0312
4.5 x 3.5	1	2	0	0.125	58	MA-515	Mark Andy	0.125
4.5 x 5.625	1	1	0	0.125	46	MA-131	Mark Andy	RECTANGLE
4.5 x 5.75	1	2	0	0.125	94	PR-80	Propheteer	0.125
4.5 x 5.75	2	2	0.125	0.125	94	PR-3	Propheteer	0.125
4.5 x 6.13	1	2	0	0.12	100	MA-543	Mark Andy	0.125
4.5 X 6.5	1	1	0.125	0.125	106	6WR-320	650	0.125
4.5 x 6.5	1	1	0	0.125	53	MA-167	Mark Andy	RECTANGLE
4.5 x 7	1	1	0	0.125	114	6WR-167	650	0.125
4.5 x 7	1	1	0	0.125	114	WR-107	650	0.125
4.5 x 7	1	1	0	0.125	57	MA-405	Mark Andy	RECTANGLE
4.5 x 9	1	1	0	0.125	73	MA-211	Mark Andy	RECTANGLE
4.5 x 9	1	1	0	0.125	73	MA-362	Mark Andy	RECTANGLE
4.5 x 11	1	1	0	0.125	89	MA-326	Mark Andy	RECTANGLE
4.625 x 8.25	1	1	0.125	0.125	67	MA-292	Mark Andy	RECTANGLE
4.6875 x 5.5	1	1	0	0.125	45	MA-197	Mark Andy	RECTANGLE
4.75 x 6	1	1	0	0.125	49	MA-123	Mark Andy	RECTANGLE
4.75 x 7.25	1	1	0	0.125	59	MA-129	Mark Andy	RECTANGLE
4.875 x 9.125	1	1	0	0.125	148	WR-141	650	0.125
4.875 x 20.875	1	1	0.125	0.125	168	MA-288	Mark Andy	squared
5 x 2.875	1	2	0	0.125	96	WR-99	650	0.125
5 x 3	1	2	0	0.125	100	WR-101	650	0.125
5 x 3	1	2	0	0.125	100	WR-19	650	0.3125

SIZE	AC	AR	GAP AC	GAP AR	TOOTH	DIE#	PRESS	CORNER R
5 x 3	1	2	0.125	0.125	50	MA-191	Mark Andy	RECTANGLE
5 x 3.5	1	2	0	0.125	58	MA-472	Mark Andy	0.125
5 x 4	1	2	0	0.125	132	WR-20	650	0.03125
5 x 5.75	1	2	0	0.125	94	PR-42	Propheteer	0.125
5 x 6	1	1	0	0.125	98	6WR-308	650	0.125
5 x 6	1	2	0	0.125	98	MA-496	Mark Andy	0.125
5 x 6.75	1	1	0	0.125	110	WR-74	650	0.125
5 x 7	1	1	0	0.125	114	WR-85	650	squared
5 x 7	1	1	0	0.125	57	MA-159	Mark Andy	RECTANGLE
5 x 8	1	1	0	0.125	65	MA-390	Mark Andy	0.125
5 x 8.5	1	1	0	0.125	69	MA-439	Mark Andy	0.125
5 x 10	1	1	0	0.125	162	6WR-315	650	0.125
5 x 11	1	1	0	0.125	178	6WR-270	650	0.125
5.25 x 2.25	1	3	0	0.125	114	WR-21	650	0.125
5.25 x 7.5	1	1	0	0.125	61	MA-466	Mark Andy	0.125
5.25 x 8	1	1	0	0.125	65	MA-52	Mark Andy	RECTANGLE
5.5 x 2.5	1	4	0	0.125	168	FLX-52	650	0.0625
5.5 x 5.5	1	2	0	0.125	90	PR-11	Propheteer	0.125
5.5 x 7	1	1	0	0.125	57	MA-432	Mark Andy	0.125
5.5 x 7.5	1	1	0	0.125	61	PR-4	Propheteer	0.09375
5.5 x 8.25	1	1	0	0.125	134	WR-75	650	0.125
5.5 x 11	1	1	0.125	0.125	89	MA10-48	10" M.A.	squared
5.5625 X .875	1	10	0	0.175	168	FLX-4	650	0.03125
5.7 x 8.84	1	1	0	0.16	144	WR-52	650	0.25
5.75 x 5.5	1	2	0	0.125	90	PR-54	Propheteer	0.125
5.75 x 9.625	1	1	0	0.125	78	MA-302	Mark Andy	RECTANGLE
5.75 x 10.375	1	1	0	0.125	168	6WR-304	650	0.125
5.75 x 12	1	1	0	0.125	97	PR-65	Propheteer	0.125
6 x 1.5	1	4	0	0.125	104	6WR-329	650	0.125
6 x 1.875	1	4	0	0.125	128	WR-122	650	0.125
6 x 4	1	2	0	0.125	66	MA-534	Mark Andy	0.125
6 x 5	1	2	0	0.125	82	PR-48	Propheteer	0.125
6 x 5	1	2	0	0.125	82	MA-240	Mark Andy	RECTANGLE
6 x 6	1	1	0	0.125	98	6WR-333	650	0.125
6 x 6.125	1	1	0	0.125	100	WR-22	650	0.125
6 x 7	1	1	0	0.125	114	WR-47	650	0.125
6 x 8	1	1	0	0.125	130	6WR-314	650	0.125
6 x 8.5	1	1	0	0.125	69	MA-214	Mark Andy	RECTANGLE
6 x 9.625	1	1	0	0.125	78	MA-46	Mark Andy	RECTANGLE
6.375 x 4.875	1	2	0	0.125	160	WR-148	650	0.125
6.375 x 4.875	1	2	0	0.125	80	PR-7	Propheteer	0.125
7 x 6.125	1	2	0	0.125	100	PR-8	Propheteer	0.125
7 x 11.75	1	1	0	0.125	95	PR-75	Propheteer	0.125
7.25 x 7.25	1	1	0	0.25	60	PR-79	Propheteer	0.125
7.25 x 7.75	1	1	0	0.125	63	PR-14	Propheteer	0.125
7.875 x 10.5	1	1	0	0.25	86	MA10-29	Mark Andy	0.125
8.375 x 10.875	1	1	0	0.125	88	PR-69	Propheteer	0.125